

From: [Meyer, John](#)
To: [Sanchez, Carlos](#); [Miller, Gary](#)
Subject: Fwd: San Jacinto Update to Congressionals
Date: Wednesday, March 09, 2016 9:28:19 AM

John C Meyer
Associate Director (6SF-R)
Superfund Division
214.665.6742
Cell 214.460.5897

Begin forwarded message:

From: "Vela, Austin" <Vela.Austin@epa.gov>
Date: March 9, 2016 at 9:22:16 AM CST
To: "Meyer, John" <Meyer.John@epa.gov>, "Phillips, Pam" <phillips.pam@epa.gov>, "Taheri, Diane" <Taheri.Diane@epa.gov>
Subject: San Jacinto Update to Congressionals

FYI

Per David's request, I just shared this with our congressional staffers:

The PRPs are scheduled to conduct the assessment and repair beginning on March 9, 2016, with completion on March 11, 2016, weather and tide permitting. The Potentially Responsible Parties conducted a visual inspection of the cap on February 24 and found a couple of areas where geotextile fabric did not have armored rock cover. The PRPs notified EPA on March 4 and we directed them to place additional rock over these areas and approved a plan to conduct this work under EPA oversight.

Thanks.

Austin Vela
Congressional Liaison Specialist
U.S. Environmental Protection Agency, Region 6
Office of External Affairs
Office: 214-665-9792



9769098